

# Part 1 - Departmental Coaching Stock

RDB 975000	M1003	RSO	QXA	YK	1951	30014	Lab. Coach 1
RDB 975001	M1004	RSO	QXA	YK	1951	30014	Lab. Coach 2
RDB 975002	M1005	RSO	QXA	YK	1951	30014	Lab. Coach 3
RDB 975003	Sc79998	DMBS	QWV	DCOW	1958	30368	Lab. 16 "GEMINI"
RDB 975004	Sc79999	DMCL	QWV	DCOW	1958	30369	Lab. 16 "GEMINI"
TDB 975005	E50416	MBS	QWV	WICK	1957	58666	ER General Managers Saloon (Class 109)
TDB 975006	E56171	DTSL	QWV	WICK	1957	58666	ER General Managers Saloon (Class 109)
DB 975007	M79018	DMBS	QWV	DY	1955	30123	Ultrasonic Test Car
DB 975008	M79612	DTCL	QWV	DY	1955	30124	Ultrasonic Test Car
ADB 975009	E43125	BS	QQV	YK	1955	30045	BTU Tool Van
RDB 975010	M79900	DMBS	QWV	DY	1956	30380	Test Coach "IRIS"
975011	Cancelled						
RDB 975012	M79185	MBS	QWV	DY	1954	30324	Brake Trials Coach
TDB 975013	M79250	DTC	QWV	DY	1954	30128	Staff Messroom
TDB 975014	M79252	DTC	QWV	DY	1954	30128	Staff Messroom
975015	Cancelled						
975016	Cancelled						
DB 975017	W9207	BSO	QPV	DR	1955	30170	Staff & Dormitory Coach
RDB 975018	E79047	MBS	QWV	METC	1955	30190	Plasma Torch Train
RDB 975019	E79053	MBS	QWV	METC	1955	30190	Plasma Torch Train
DB 975020	E87252	Fish Van	ZQV	EARL	1953	30125	Stores Van
ADB 975021	W9263	BSO	QPV	DR	1955	30170	Staff Coach
ADB 975022	309	Pullman	QXV	BRCW	1958	30511	HERCULES
TDB 975023	W55001	DMBS	QWV	GRCW	1958	30419	Route Learning Car
ADB 975024	W21070	BCK	QPV	METC	1854	30133	BTU Staff & Dormitory Coach
TDB 975025	S60755	TRB	QWA	EH	1958	30393	SR General Managers Saloon
975026	Cancelled						
ADB 975027	M61162	DMBS	EZ5X	EHGE	1957	30326	Test Coach Stock Trials
ADB 975028	M70162	TS	EZ5X	EHGE	1957	30327	Test Coach
ADB 975029	M75162	DTBS	EZ5X	EHGE	1957	30328	Test Coach
ADB 975030	M61165	DMBS	EZ5	EHGE	1957	30326	Test Coach
ADB 975031	M70165	TS	EZ5	EHGE	1957	30327	Test Coach
ADB 975032	M75165	DMBS	EZ5	EHGE	1957	30326	Test Coach "MARS"
ADB 975033	W9214	BSO	QPV	DR	1954	30170	BTU Staff & Tool Van
ADB 975034	W9215	BSO	QRV	DR	1954	30170	Enparts Van (Ex.FVV B745088)
ADB 975035	W9219	BSO	QRV	DR	1954	30170	Enparts Van
RDB 975036	W9234	BSO	QXV	DR	1954	30170	(Lab. Coach 22)
ADB 975037	W9251	BSO	QRV	DR	1954	30170	Enparts Van
ADB 975038	W9258	BSO	QRV	DR	1954	30170	Enparts Van
ADB 975039	W9264	BSO	QRV	DR	1954	30170	Enparts Van
ADB 975040	W9265	BSO	QRV	DR	1954	30170	Enparts Van
ADB 975041	W9266	BSO	QRV	DR	1954	30170	Enparts Van
TDB 975042	M55019	DMBS	QWV	GRCW	1968	30518	Sandite Unit
ADB 975043	W9247	BTO	QRV	DR	1954	30170	Enparts Van
975044	Cancelled						
975045	Cancelled						
RDB 975046	S34249	BSK	QXX	AFEH	1950	30021	Lab. Coach 11
KDB 975047	W34769	BSK	QPV	WO	1954	30157	S&T Staff & Dormitory Coach
975048	Cancelled						
ADB 975049	E34290	BSK	QRV	WO	1952	30065	Stores Coach
ADB 975050	M34020	BSK	QXX	DY	1950	30003	Test Coach
ADB 975051	M34133	BSK	QXX	WO	1950	30025	Test Coach 5
ADB 975052	M34295	BSK	QXX	WO	1952	30065	Test Coach
ADB 975053	E34180	BSK	QRV	WO	1950	30025	Stores Coach
ADB 975054	E9200	BSO	QPV	DR	1954	30170	BTU Staff Coach
ADB 975055	E70584E	BG	QQV	YK	1945	Dia.327	BTU Tool Van
ZDB 975056	M96300	HB	QXV	EARL	1954	30146	Cinema Coach Generator Van
DB 975057	S34635	BSK	QPV	CROB	1954	30143	Staff & Dormitory Coach
DB 975058	S34619	BSK	QPV	GRCW	1954	30142	Staff & Dormitory Coach
DB 975059	W34800	BSK	QPV	WO	1954	30157	Staff & Dormitory Coach
DB 975060	W34861	BSK	QPV	GRCW	1955	30220	Staff Coach